	Туре	Hits	Search Text
1	BRS	102360	aircraft airplane helicopter
2	BRS	5031	wind near3 (turbine mill motor drive)
3	BRS	112136	aircraft airplane helicopter
4	BRS	6126	<pre>wind near3 (turbine mill motor drive)</pre>
5	BRS	12956	wind near3 (turbine mill motor drive)
6	BRS	218113	aircraft airplane helicopter
7	BRS	1286	S5 and S6
8	BRS	506	S7 and (generator alternator dynamo)
9	BRS	173	S8 and battery
10	BRS	1047	wind near3 (turbine mill motor drive)
11	BRS	11389	aircraft airplane helicopter
12	BRS	27	S10 and S11
13	BRS	1540	wind near3 (turbine mill motor drive)
14	BRS	8097	aircraft airplane helicopter
15	BRS	9	S13 and S14
16	BRS	85639	aircraft airplane helicopter
17	BRS	14803	wind near3 (turbine mill motor drive)
18	BRS	179	S16 and S17
19	BRS	36	S18 and (generator alternator dynamo)

	DBs	Time Stamp	Comments	Error Definition
1	USPAT	2005/06/08 14:00		
2	USPAT	2005/06/08 09:07		
3	USPAT	2005/06/08 09:08		
4	USPAT	2005/06/08 09:07		
5	US-PGPUB; USPAT; USOCR	2005/06/08 14:02		
6	US-PGPUB; USPAT; USOCR	2005/06/08 14:00		
7	US-PGPUB; USPAT; USOCR	2005/06/08 09:08		
8	US-PGPUB; USPAT; USOCR	2005/06/08 14:02		
9	US-PGPUB; USPAT; USOCR	2005/06/08 14:03		
10	EPO	2005/06/08 09:52		
11	EPO	2005/06/08 09:53		
12	EPO	2005/06/08 09:47		
13	JPO	2005/06/08 09:56		
14	JPO	2005/06/08 09:55		
15	JPO	2005/06/08 09:53		
16	DERWENT	2005/06/08 09:55		
17	DERWENT	2005/06/08 09:56		
18	DERWENT	2005/06/08 09:56		
19	DERWENT	2005/06/08 09:56		

	Туре	Hits	Search Text
20	BRS	14 1 85 4	S6 and (generator alternator dynamo)
21	BRS	6829	S20 and battery
22	BRS	6656	S21 not S9
23	BRS	1442	S22 and auxiliary
24	BRS	1X h h	S23 and (lightening hvac (air adj condition\$4) computer radio)

	DBs	Time Stamp	Comments	Error Definition
12.0	US-PGPUB; USPAT; USOCR	2005/06/08 11:14		
12.1	US-PGPUB; USPAT; USOCR	2005/06/08 11:14		
22	US-PGPUB; USPAT; USOCR	2005/06/08 11:15		
23	US-PGPUB; USPAT; USOCR	2005/06/08 11:16		
12.4	US-PGPUB; USPAT; USOCR	2005/06/08 11:17		